



Drop shell one at a time into tube until the desired amount is in tube.



Push shells unto gate until rifle is full.




Place tube over gate and hold thumb here, opposite hand.



Top of Rifle

Push shells into gate until loader is empty.




Detail III



Detail III





Detail I




Detail II



OVER ALL DRAWING



Detail I



Detail II



Detail III



ANY UNAUTHORIZED MODIFICATIONS WILL VOID ALL WARRANTIES ON THIS PRODUCT.